





Bez.: Montageanleitung 30

	
1. 	Preparation of cable (1) Slide crimp ferrule onto cable. (2) Strip cable to recommended dimensions shown in catalogue.
2. 	Crimp center contact to cable center conductor (1) Insert cable center conductor into center contact until it butts against cable dielectric. (2) Crimp (or solder) center contact.
3.  All braid wires on outside of inner ferrule	Attach cable to connector body (1) Insert cable assembly into rear of connector body, with all braid wires on outside of inner ferrule. (2) Push cable assembly forward until contact snaps into place in insulator.
4. 	Final assembly (1) Slide crimp ferrule forward until flush with connector body and crimp.

www.bkl-electronic.de

Technische Änderungen vorbehalten. Ausführungen können variieren. Sollten Sie ein Muster benötigen kontaktieren Sie uns bitte.

BKL-ELECTRONIC Kreimendahl GmbH • Märkenstück 14 • 58509 Lüdenscheid

Tel: +49 (0)2351-3621-0 • Fax: +49 (0)2351-3621-29 • info@bkl-electronic.de

